SpotCheck Handheld SMD Reel Estimator (Reel Counter), Model 25050



Exclusively Distributed, Serviced in India by Inde Enterprises





The SpotCheck™ Reel Estimator quickly determines counts to within 5%. This is an affordable handheld meter designed for inventory management and job setup to determine tape and reel part counts. This meter provides accurate estimates without the cost or complexity of a bench top counter.

Features

- Suits for all tape widths/thicknesses/component types
- Works with both 7" (18cm) & 13" (33cm) reels

Indian

istributor

- Estimates component counts to within 5%
- · Self-contained, handheld, battery powered
- Patented Design (US Patent #8,245,412)
- CE and RoHS Compliant
- Made in USA

Specifications

Tape & Reel Requirements : Requires standard 4mm pitch feed holes on tape and 13mm center hole in reel.

Fits Reel Sizes : 7 inch(18cm) and 13 inch(33cm) reels

Gauge

Note: 15 inch(38cm) reels possible with user supplied ruler

: 2mm to 40mm part spacing on tape (Pitch) **Fits Part Spacing**

Accuracy : +/- 5% on part count

: One (1) 9 volt size alkaline battery 1 Year Battery Life or Approx 1000 readings **Battery**

Meter Size : 7.5in(19cm) x 4in(10cm) x 1in(2.5cm)

Meter Weight : 0.4lbs(180 g)

Environmental : at 32-104*F(0-40*C) with 0-90% RH


How it works:

- 1) Place gauge plate into center hole of reel. Read the outer diameter of the tape wrapped on the reel. Enter this number as the OD value.
- 2) Read the inner diameter of the first wrap of tape. This is also the diameter of the hub of the reel. Enter this number as the ID value.
- 3) Count the number of feed holes between the centers of two consecutive parts & enter this as the holes value. Very small parts will only have one hole per two parts so this would be entered as 0.5 on the LCD.
- 4) Use the gauge plate to measure the thickness of the tape. Be sure to be very accurate with this measurement and don't forget to measure the full thickness of the tape including the thickness of removable cover film. For thin tape use the slots of the gauge plate. For thicker tape use the ruler along the back edge of the gauge plate. Best results are achieved by unwinding a short leader of tape to accurately determine which slot is the best fit on the gauge plate.

(NOTE: while estimates of thin tape are possible by visual comparison to slot widths without unwinding any tape, this method often leads to greater error in the count)

5) Once all measurements have been accurately set the PART COUNT will be correctly displayed on the LCD. To count another reel simply change only the values that differ on the LCD. (For similar parts it may only be necessary to change the OD value for each reel being counted.)







Video available at www.indeonline.in, Call us for demo